


1 West 67<sup>th</sup> Street Presentation to the Preservation Committee of Community Board 7


#### Hotel Des Artistes – 1917

The Hotel des Artistes was completed in 1917, following the lead of several other buildings on the block it was intended as livework space for artists. The buildings gothic 67<sup>th</sup> street façade boasted south facing double-height windows that would have been coveted by artists.



### Hotel Des Artistes – Today

While the spirit of the existing design remains, many apartments have replaced their windows over the years leaving the façade a mishmash of designs and operations.




Hotel Des Artistes - 1917



Hotel Des Artistes - Today









 $Horizontal\ Pivot\ {\rm it\ swings\ equally\ to\ the\ interior\ and}$ 

exterior via a pivot on the center horizontal axis. Muntins divides the glass into four panes






Fixed Unit with Muntins divides the glass into four panes






The Middle Row is still the original steel frame with divided lights with milky cast textured glass. The character of these units cannot be replicated and therefore are not a part of this proposal.






 $Out-swing\ Casements\ {\tt windows\ open\ from\ the\ center}$ 


out on a vertical pivot







Fixed Unit with one Muntin dividing the glass in half












#

Proposed East Bay





Proposed East Bay





**1917** All three windows at the top row were divided by muntins into four lights each. The center window was fixed and the two outer windows operated as horizontal pivots.

**Proposal** All three windows are proposed to be divided by a simulated muntin to re-create the existing design. The exception taken to the original design is the operation of the two outer windows.

Top Row







#### Interior

### Horizontal Pivot –


While this was the operation of this window in 1917, building standards have changed significantly since. This operation will not provide acceptable thermal performance, or acoustic separation. For these reasons this window is not commercially manufactured and would have to be custom engineered.


Additionally it does not allow for the use of an interior sun shade or curtain, which is necessary for a south facing window.


## Awning –

This window re-creates the 1917 window design, however by changing the operation of the window to an outswing awning the thermal and acoustic performance of this window will perform to toady's standards. Since there is no component of this window that swings into the room, a shade or curtain can be used.

## Window Operation








# Proposed East Bay

Both the West Bay and East Bay are proposed to be identical

# #

11




ORIG TO REMAIN

TOTAL

1/4" ]

**1917** T he three windows at the bottom row were divided once in the middle, the two outer windows operated as out-swing casements and the center window was fixed.




2

TOTAL

3/8"

Bottom Row

3 3/8" 101/



Window Construction - The 1917 window bays are structured by steel plates that run horizontally and vertically, dividing the bay into the nine smaller window units. Our proposal is to save and restore this frame then infill it with new windows. The proposed windows are thermally broken steel frames with insulated glass units. In the details above the grey tones are the existing frames that will remain.