


HISTORIC DISTRIC MAP



OASIS MAP



PROJECT LOCATION




STREET VIEW looking NE




CURRENT SCHOOL BUILDING








WALDEN DESIGN RENDERING c: 1967 - 73




WALDEN - 1987 (CARRIEANNEBROWNIAN.COM)







EXISTING SIDEWALK VIEW LOOKING NW



EXISTING BUILDING ENTRY



CURB VIEW BUILDING ENTRY



EGRESS STAIR LANDING AT ENTRY







DETERIORATING CONCRETE WALL



SPALLED CONCRETE WALL



VIEW OF RUSTING METAL STAIR





WALL DETERIORATION




LANDING BEAM & STAIR CONDITION

Sheet 6 of 9


















BUILDING ENTRY MODIFICATION for ADA ACCESS



SIDEWALK VIEW of RAMP & ADA CHAIR LIFT



STREET VIEW of RAMP & ADA CHAIR LIFT