






NORTH MEADOW CENTER







1934 ROAD INTO YARD NORTH MEADOW CENTER







CENTRAL PARK GETS MORE PLAY AREAS

New York Times 1857-Current; May 18, 1934; ProQuest Historical Newspapers The New York Times (1851 - 2001) pg. 5

CENTRAL PARK GETS MORE PLAY AREAS

Digging Plots Set Aside for Children—15 Baseball Fields to Be Ready Soon.


BOWING TO CRITICS DENIED

Moses Says Plans Were Made Some Time Ago—Complaints From 'Defenders' Expected.

An increase in active play facilities in Central Park was announced yesterday by the Park Department, following recent criticism of the department for failure to make adequate provision in the park for children. Park Commissioner Moses denied, however, that any connection existed between the announcement and the criticism.

"There is absolutely no relationship," he declared. "We are merely making public now detailed plans for improvements we had mentioned some time ago."

NEW PLAYGROUNDS UNDER CONSTRUCTION IN CENTRAL



Peter Juley & Son Photo.

An Architect's Drawing Showing a Birdseye View of the Baseball Diamonds and Additional Play Facilities

Now Under Way.



1936 WEST WING ENTRANCE NORTH MEADOW CENTER



1936 WEST WING NORTH MEADOW CENTER




1965 BIRDSEYE VIEW NORTH MEADOW CENTER



PROJECT PURPOSE

- Renovate public facilities (recreation courts and restrooms)
- Renovate and optimize vitally-needed park operations space
- Site work to support and screen park operations

PUBLIC RECREATION





YOUTH BASKETBALL COURTS








HANDBALL COURTS NORTH MEADOW CENTER




BUILDING





EXISTING FLOOR PLAN

NORTH MEADOW CENTER



PROPOSED FLOOR PLAN NORTH MEADOW CENTER






PROPOSED

SCOPE OF WORK

- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- (3) MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- **5** SELECT MASONRY REPAIRS

- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- **8** EXTERIOR LIGHTING REPLACEMENT
- (9) IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)




SOUTH ELEVATION






A - SOUTHWEST ELEVATION

B - SOUTHEAST ELEVATION






EXISTING SOUTHWEST




PROPOSED SOUTHWEST

- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- (3) MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- **5** SELECT MASONRY REPAIRS

- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- **8** EXTERIOR LIGHTING REPLACEMENT
- 9 IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING




EXISTING SOUTHEAST



PROPOSED SOUTHEAST

- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)







C - COURTYARD SOUTHWEST



CD


D - COURTYARD SOUTHEAST






- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- **3** MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- 5 SELECT MASONRY REPAIRS

- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- **8** EXTERIOR LIGHTING REPLACEMENT
- 9 IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)








E - COURTYARD WEST



F - COURTYARD EAST










- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- 3 MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- **5** SELECT MASONRY REPAIRS

- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- 8 EXTERIOR LIGHTING REPLACEMENT
- 9 IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)










- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- **3** MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- **5** SELECT MASONRY REPAIRS

- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- **8** EXTERIOR LIGHTING REPLACEMENT
- 9 IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)








PROPOSED

SCOPE OF WORK

- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- **3** MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- **5** SELECT MASONRY REPAIRS

- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- **8** EXTERIOR LIGHTING REPLACEMENT
- 9 IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)




NORTH ELEVATION




I - NORTH WEST ELEVATION




J - NORTH EAST ELEVATION




BUILDING ELEVATIONS NORTH MEADOW CENTER







- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- 3 MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- **5** SELECT MASONRY REPAIRS

- 6 GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- 8 EXTERIOR LIGHTING REPLACEMENT
- (9) IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)








PROPOSED

- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- 3 MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- 5 SELECT MASONRY REPAIRS


- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- 8 EXTERIOR LIGHTING REPLACEMENT
- 9 IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)






G - EAST ELEVATION






H - WEST ELEVATION

EAST AND WEST ELEVATIONS NORTH MEADOW CENTER






1 KOI OSE


1 SLATE ROOF REPAIRS


SCOPE OF WORK

- 2 SNOW GUARD REPLACEMENT
- **3** MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- **5** SELECT MASONRY REPAIRS

- **6** GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- **8** EXTERIOR LIGHTING REPLACEMENT
- 9 IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS. MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)









SCOPE OF WORK


- 1 SLATE ROOF REPAIRS
- 2 SNOW GUARD REPLACEMENT
- 3 MASONRY CLEANING
- 4 SELECT MASONRY REPOINTING
- 5 SELECT MASONRY REPAIRS

- 6 GUTTER AND LEADER REPLACEMENT
- 7 CAST IRON COLUMN RESTORATION
- **8** EXTERIOR LIGHTING REPLACEMENT
- (9) IN KIND WINDOW AND DOOR REPLACEMENT U.O.N.
- 10 NEW FULL HEIGHT WINDOW PANEL @ EXISTING DOOR OPENING
- 11 NEW DOORS @ EXISTING WINDOW OPENINGS.
 MODIFY MASONRY AS NEEDED.
- 12 TRANSLUCENT FILM APPLIED ON GLAZING AT BATHROOMS / LOCKER ROOMS (SHOWN IN GREY)






HISTORIC ELEVATION 1936 DOOR PROFILE




PROPOSED ELEVATION
PROFILE TO MATCH 1936 DOOR PROFILE


*ALL DIMENSIONS TO BE V.I.F.



HISTORIC ELEVATION 1936 DOOR PROFILE




PROPOSED ELEVATION
PROFILE TO MATCH 1936 DOOR PROFILE



PROPOSED ELEVATION
PROFILE TO MATCH 1936 DOOR PROFILE

*ALL DIMENSIONS TO BE V.I.F.



PROPOSED ELEVATION
PROFILE TO MATCH EXISTING
FIXED WINDOW TO REPLACE OPERABLE WINDOW
LIGHTWEIGHT STEEL MESH REPLACING GRILLES

PROPOSED ELEVATIONFIXED WINDOW WITH PANEL


2' - 9"


(W2)


*ALL DIMENSIONS TO BE V.I.F.
*TRANSLUCENT FILM APPLIED ON INTERIOR OF
GLAZING AT RESTROOMS AND LOCKERS


HISTORIC PARTIAL ELEVATION

1936 WINDOW PROFILE









HISTORIC ELEVATION
1936 DOUBLE HUNG WINDOW PROFILE

PROPOSED ELEVATION
PROFILE TO MATCH EXISTING DOUBLE HUNG


PROPOSED ELEVATION
PROFILE TO MATCH EXISTING DOUBLE HUNG


(W3b)


PROPOSED ELEVATION
PROFILE TO MATCH EXISTING DOUBLE HUNG

(W3c)

*ALL DIMENSIONS TO BE V.I.F.
*TRANSLUCENT FILM APPLIED ON INTERIOR OF
GLAZING AT RESTROOMS AND LOCKERS









HISTORIC ELEVATION
1936 CASEMENT WINDOW PROFILE


PROPOSED ELEVATION
PROFILE TO MATCH EXISTING DOUBLE HUNG

 $\langle W4 \rangle$



*ALL DIMENSIONS TO BE V.I.F.
*TRANSLUCENT FILM APPLIED ON INTERIOR OF
GLAZING AT RESTROOMS AND LOCKERS

SITEWORK FOR PARK OPERATIONS



CURRENT AERIAL VIEW NORTH MEADOW CENTER









PARK OPERATIONS VEHICLES NORTH MEADOW CENTER










PARK OPERATIONS STORAGE

NORTH MEADOW CENTER
























PROPOSED

SOUTH ELEVATION





PROPOSED



EXISTING SOUTHEAST CORNER







VIEW TO SOUTHEAST CORNER NORTH MEADOW CENTER



