



1940's tax photo of 113 West 77th Street
This photo shows the original configuration
of the windows and the areaway wall



Designation Photo taken at the time the violation was issued



**Streetscape – Facing
West 77th Street**



3rd floor Windows



2nd floor Windows

Top

Middle

Bottom



Front Elevation



3rd Floor Windows



2nd Floor Windows



115 W 77th



113 W 77th



111 W 77th



121 W 77th



123 W 77th



Close up of window molding

