

# 127 West 88<sup>th</sup> Street

## Upper West Side Historic District

Landmarks Preservation Commission

LPC 181047


Block: 1219      Lot: 19

### Request For Certificate of Appropriateness For:

Legalizing an areaway fence installed without Landmarks Preservation  
Commission Permits

8.18.2016

1




**127 West 88<sup>th</sup> Street**

8.18.2016

2



Designation Photograph



Current Photograph



**127 West 88<sup>th</sup> Street**

8.18.2016



**Areaway Fence 1960's**



**Areaway Fence 2015**



**127 West 88<sup>th</sup> Street**

8.18.2016

4





## Precedence on West 88<sup>th</sup> Street part 1

8.18.2016





## Precedence on West 88<sup>th</sup> Street part 2

8.18.2016

6






## Precedence on West 88<sup>th</sup> Street part 3

8.18.2016





**1960's Front elevation**






**127 West 88<sup>th</sup> Street 1960's conditions**

8.18.2016

8






**2015 Fence plan and elevations + view**

8.18.2016





1940

**Historical picture**

8.18.2016

10





11.1 North side



11.2 North side



11.3 North side looking East



11.4 North side looking East

## 127 West 88<sup>th</sup> St views of block part 1

8.18.2016

11





12.1 North side



12.2 South side



12.3 North side looking West



12.4 North side



12.5 North side looking West

## 127 West 88<sup>th</sup> St views of block part 2

8.18.2016

12





13.1 South side



13.2 South side looking West



13.5 South side



13.3 South side looking West




13.4 South side looking East

## 127 West 88<sup>th</sup> St views of block part 3


8.18.2016

13





1960's




2015

127 West 88<sup>th</sup> Street

8.18.2016

14





## 127 West 88<sup>th</sup> St restorative works part 1

8.18.2016

15





## 127 West 88<sup>th</sup> St restorative works part 2

8.18.2016

16





**127 West 88<sup>th</sup> St restorative works part 3**

8.18.2016

17





# 127 West 88<sup>th</sup> St restorative works part 4

8.18.2016 18




**127 West 88<sup>th</sup> St restorative works part 5**

8.18.2016

19





**127 West 88<sup>th</sup> St restorative works part 6**

8.18.2016


20





## Block 1219 88<sup>th</sup>St Entrances typologies





## Fences typologies keyplan