6-16 West 77th Street New York

LPC - Design Update January 25th 2022

Massing As Presented - Nov 16th 2021



Comments Received - Nov 16th 2021

- Studio (Level 18) South face not a challenge in regards to visibility but North & Park faces could be revised
- Lower Penthouse (Level 17 + 18)
- Lower Height to reduce visibility (Level 18)
- Revised location of Level 18 (Like a Cupula) maybe move back, address elevator overrun (east)
- Video to demonstrate how visible it is

Massing As Presented - Nov 16th 2021




Revised Scheme




Revised Scheme




Current Elevation




Massing As Presented - Nov 16th 2021




Revised Massing




Main Facade Comparison







Section A-A' - Revised Massing



Section Comparison















As Presented Revised


Revised - Level 18




Level 18 Comparison



Level 17 - Outline As Presented - Nov 16th 2021




Level 16 - Outline As Presented - Nov 16th 2021



Revised Scheme







Massing As Presented - Nov 16th 2021



Revised Scheme





As Presented Revised

Massing As Presented - Nov 16th 2021



Revised Scheme





As Presented Revised

Massing As Presented - Nov 16th 2021 - Central Park West (Winter Condition)



Revised Scheme - Central Park West (Winter Condition)





As Presented Revised

Massing As Presented - Nov 16th 2021 - Central Park (Winter Condition)

Revised Scheme - Central Park (Winter Condition)



As Presented Revised

Street View Comparison - 76th view





As Presented Revised

34

Street View Comparison - Central Park West view





As Presented Revised


35

FILM

Appendix

Visibility Studies

- No visibility
- Limited visibility



6-16 West 77th Street, Mock Up




Mock-Up



Facade Maintenance Rigging

Primary Facade - Mock Up









02 - Visibility Studies - Mock Up





03 - Visibility Studies - Mock Up



04 - Visibility Studies - Mock Up



05 - Visibility Studies - Mock Up

06 - Visibility Studies - Mock Up




07 - Visibility Studies - Mock Up




Construction Logistics


- Detailed Site Safety and Logistics plans developed and promulgated to address stringent public safety protocols, including overhead protection, sidewalk bridge, pedestrian access, and more.
- Throughout the anticipated construction period of 18 months, the project manager will communicate regularly with residents of 6-16 West 77th Street as well as immediate neighbors to provide advance notice of any work which may create short-term inconveniences.
- Comprehensive protection plan for both 6-16 West 77th Street and adjacent New-York Historical Society, ensuring implementation of maximum protections to historic building fabric during demolition and construction.
- Diligent attention to quality-of-life issues throughout demo and construction, including access and egress to building, debris removal, vermin control, noise and dust, etc.
- Use of best-in-class means, methods and products to address all thermal, moisture and waterproofing of the project.
- Coordinate closely with adjacent New-York Historical Society, explore opportunities for collaboration in order to reduce the impact of temporary inconveniences on neighbors, eliminate redundancies, and assist with project logistics and construction schedule.









Level 16 - Comparison



Level 17 - Comparison



Level 18 - Comparison





Floor Area Summary

TOTAL

ı	Floor	Existing	Proposed Floor	Reloca	Notes
	Designations per	Floor Area	Area (complied w/ Zoning FA)	Floor Area	
	marketing				
	Level 16	1.857SF	1.549SF		
	Level 17	3.417SF	3091 SF	-326 SF	
	Level 18	none	634 SF		
		5,274 SF	5,274 SF	0 SF	