## 173-175 Riverside Drive, Manhattan



2<sup>nd</sup> Floor Spandrel Panel Replacement (Master Plan)

Location 173-175 Riverside Drive, Manhattan





The property occupies the full block between 89th and 90th Streets along Riverside Drive

Historic Conditions 173-175 Riverside Drive, Manhattan



1940s tax photo



Historic photo - National Park Service archives

Existing Conditions 173-175 Riverside Drive, Manhattan



Existing spandrel panels along west (Riverside Drive) façade



Existing spandrel panels along north (90th Street) façade

Existing Conditions 173-175 Riverside Drive, Manhattan



Existing spandrel panel – wood rot, paint failure



Existing spandrel panel – paint failure

Existing Conditions 173-175 Riverside Drive, Manhattan



Existing modified spandrel panel – note the louver stops roughly 6" short of the jamb at either side, leaving remnants of the original spandrel panels




Existing modified spandrel panel – note louver encompasses nearly the entire width of the opening; this is the general intent for future louver installations

**Work Being Proposed** 




North façade – 10 out of 10 existing unmodified panels to be supplied with new limestone panels

South façade – 8 out of 13 existing unmodified panels to be supplied with new limestone panels; the remainder have existing penetrations for through-wall AC




West façade – 17 out of 26 existing unmodified panels to be supplied with new limestone panels; the remainder have existing penetrations for through-wall AC

Work Being Proposed 173-175 Riverside Drive, Manhattan



Details: Existing and Proposed Spandrel Panels

Work Being Proposed 173-175 Riverside Drive, Manhattan



Details: Existing Spandrel Panel, Proposed New Louver

Appendix 173-175 Riverside Drive, Manhattan



Upper façade detail - existing 15th floor spandrel panel

Appendix 173-175 Riverside Drive, Manhattan





Probe/removals at existing spandrel panel